




X




✓











X






✓




1





2

C1  Ø8
x8**C2**  Ø5
x4**K**  x12


3




4



5



6



O




Ø20

x4



B1

B2


7






8





x2



9



10



11

